



SpeedX 115 MANUAL

System parts

- Guide
- Reaming bit
- Pilot bit
- Locking pin 2 pcs
- O-ring 2 pcs



Disassembly

1. Use suitable O-ring hook to remove the O-rings from both holes in the pilot bit.



Push out the locking pins by inserting a suitable tool through the smaller holes in the pilot bit.



3. Remove pilot and reaming bits.



Assembly

1. Install reaming and pilot bits with the "wear pad" of the pilot bit on the reverse side of the reaming bit's outer position.



2. Push locking pins in place.




3. Mount the O-rings in their seats outside the locking pins. Use some lubricant and suitable tool to avoid damaging the O-ring during mounting. Never mount a used O-ring!



4. Make sure the O-ring is perfectly seated.





Box 205 682 31 Filipstad

Phone +46 590 10178 Fax +46 590 607084 www.allroc.se

SpeedX is protected under Swedish patent No. 0400929-6.

Patent pending in other countries.